

|   | Type | L # | Hits | Search Text  | DBs   | Time Stamp       |
|---|------|-----|------|--|---|------------------|
| 1 | IS&R | L1  | 3    | (("6633148") or ("6573676") or ("6605911")).PN.      | US-<br>PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO | 2006/03/07 12:04 |
| 2 | BRS  | L2  | 13   | inverter and sensor and earth near3 plate and ground | US-<br>PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO | 2006/03/07 12:06 |
| 3 | BRS  | L3  | 2    | inverter and sensor and earth near3 plate and 0v     | US-<br>PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO | 2006/03/07 12:07 |
| 4 | BRS  | L4  | 3499 | tool and ground near3 wire                           | US-<br>PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO | 2006/03/07 12:07 |
| 5 | BRS  | L5  | 228  | tool and ground near3 wire and inverter              | US-<br>PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO | 2006/03/07 12:41 |
| 6 | BRS  | L7  | 40   | 0v near4 ground and tool                             | US-<br>PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO | 2006/03/07 12:44 |

|    | Type | L # | Hits | Search Text                | DBs   | Time Stamp       |
|----|------|-----|------|----------------------------|---|------------------|
| 7  | BRS  | L6  | 2044 | 0v near4 ground            | US-<br>PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO | 2006/03/07 13:48 |
| 8  | BRS  | L8  | 320  | 0v and ground and tool     | US-<br>PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO | 2006/03/07 13:59 |
| 9  | BRS  | L9  | 1215 | 0v and ground and sensor   | US-<br>PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO | 2006/03/07 14:05 |
| 10 | BRS  | L10 | 139  | 0v and ground near5 sensor | US-<br>PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO | 2006/03/07 14:06 |